


Six Steps To Spray Starch Success



1 Line up nozzle
with red dot



2 Shake can



3 Tilt slightly
never more than 45°
from an upright position



4 Proper distance
of 6"-10" from
garment



5 Press nozzle
firmly, and
spray fabric
lightly



6 Wash spray
button when
finished